

May 18 1886

I commenced Survey of Section 18 Town 7 North, Range 6 West.

Francis M Parker
County Surveyor.

For Peter Schultz et al

COURSE.	DISTANCE.	REMARKS.	
South	40.08	From E¼ section 18 section corner	
	120.65	S E sec 19	3° 5'
West-	40.17	From SE 18 Stone	
	86.30	S W	3° 45'
North		From E¼ section 13-7-7	
North	40.20	N E From E¼ 18	3° 57'
	80.16	E¼ sec. 7	
West-		From N ¼ sec 17	
West-	40.10	N W 17	4°
	40.36	From N E 18 Found stone 12 links north which I think incorrect	
	49.00	on Buck Creek	
	85.88	intersect Range line 72 links South of corner of sec. 12 & 13-7-7 which I make the proper Cap	
North		From S¼ Sec 18 to Buck Creek	
	35.00		
	80.04	N¼ N E	3° 30'

Corners Established.	Monument.	Bearing Trees.	Diameter in Inches.	Course.	Links Distant.	
N E sec 18	@ ditch Stone in	Elm		S 85 E	18	Double in Stone
S E	Stone is	N E Corner of Sec- East 124 lks		about two feet		
S ¼ S E	Stone	Jack Oak	4	S 78 W	135	
S ¼ N E		Elm	4	S 6 E	67	
		Bur Oak	12	S 31 W	142	
cen. S E		Bl Oak	15	N 89 W	29½	
W ¼ S W	Stone	Hickory	15	N 14½ W	74	W¼ S W 18
W ¼ N W	Stone	Hickory	5	N 35 E	75	4½ N W 18
		Elm	6	S 40 E	73	
N ¼ N E	Stone	W Oak	5	S 27 E	380½	
cen. N E	Stone					
S ¼ S W	Stone					
N W	corner	12 and 13-7-7		North	72	

section 19-7-6

Having made an exhaustive investigation to prove the position of the original corner at the S E corner of section 19-7-6 in the above survey I urged that a stone be put in to perpetuate the corner this duty was delegated to Mr J.H. Taylor supervisor of roads it being in the public highway he subsequently sent me the following notice

Oct 13 '86 Mr Frank Parker Bloomfield Ind

I put the corner stone in on the corner of sec 30 18 & 19 as you requested F.M. Hinbrook Thomas Ellis A.J. Gastineau witnesses You can record it as you said you would J H Taylor

The reference to section 10 is I guess a mistake

F M Parker C. S.

S E 19 stone